


# Repair Parts Sheet

## BWF888 Sidewinder® Bender



#### **Parts List**


Item Number	Part Number	Number Required	Description	on
1	BWF800 ···Includes ···	1	Frame Assembly	
2		4	Lock Washer	<sup>3</sup> ⁄8" dia.
3		4	Washer	<sup>13</sup> ⁄ <sub>32</sub> " dia.
4		4	Capscrew	<sup>3</sup> ⁄8" - 16 x 1"
5	ZCK651900	1	Undercarriage Assembly	
6	ZC124106 ···Includes ···	2	Wheel	
		2	*Cotter Pin	<sup>13</sup> ⁄ <sub>32</sub> " x 1"
		4	*Washer	<sup>13</sup> ⁄ <sub>32</sub> "

<sup>\*</sup>Common Replacement Parts

### BWF888 Parts List

Item	Part	Number	
Number	Number	Required	Description
1	BWF800	1	Frame Assembly
_	··· Includes ···	-	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
2	ZCK13900	1	Frame
4	ZCK86026	1	Instruction Decal 1 of 2
5 6	ZCK867026	1	Instruction Decal 2 of 2
6	ZCM240026	1	Release Decal
7	ZCL893108	1	Retaining Washer
12	B1152057	1	Spring Pin
31 41	CK304104 ZF67123	1	Shaft Nut Bachet
44	ZCL970225	1	Nut, Rachet Shaft
45	ZB1132057	2	Pins
	201102007		1 1113
13	BF49 ···· Includes ···	1	Ratchet Assembly
40	ZCK103111	1	Bracket Assembly w/pin
42	ZCK578044	i	Retaining Ring
14	BW72	1	Lever Kit
	··· Includes ···	-	
15	ZCM243070	1	Lever
16	ZB1084108	2	Flat Washer
18	ZCK29110	1	Spring
19	ZCL382061	1	Clevis Pin
20	ZCK24305	1	Drive Stud
21	BW74	1	Drive Pawl Kit
22	··· Includes ··· ZCR231885	4	Drive Pawl
23	ZCK30110	1	Spring
24	ZF28900	1	Rivet Plate
25	ZCR307028	1	Capscrew
26	BW75	i	Hold Pawl Kit
	··· Includes ···		
27	ZCK230885	1	Hold Pawl
28	ZCK30110	1	Spring
29	ZF28900	1	Rivet Plate
30	ZCK307028	1	Capscrew
32	BF41 (also includes BF47)	1	Roller & Shaft Assembly
00	··· Includes ···	4	Hrothana Dallay/Cat Dallay
33	ZCM260281	1	Urethane Roller/Soft Roller
34	ZCM105268	1	Roller Tube
35 36	ZCK380044 ZCK580107	2 2	Retaining Ring Retaining Washer
	ZUN360107		Hetaining washer
8	BW76 ··· Includes ···	1	Pin Kit
9	ZCM47061	1	Spring
10	ZCM47061	i	Pin
11	ZB1055057	2	Pin

Item Number	Part Number	Number Required	Description
37	BF47 ··· Includes ···	1	Shaft Assembly
38	ZB1138057	1	Pin
39	ZCL892058	1	Cotter Pin
43	ZCM101061 Includes	1	Shaft
	ZCK292107	2	Bearings



#### **Bending Shoes**,



**BT57510** ½" - ¾" - 1" Thinwall

- 1. Jaw BZ1306
- 2. Chain NSS



**BT12515** 1½" - 1½" Thinwall

- 1. Jaw BZ1307
- 2. Chain NSS
- 3. Tooth Insert BTI12520



**BR57510** ½" - ¾" - 1" Rigid

- 1. Jaw BZ1306
- 2. Chain NSS



**BR12515** 1½" - 1½" Rigid

- 1. Jaw BZ1307
- 2. Chain NSS
- 3. Tooth Insert BTI12520



BR20000 2" Aluminum

- 1. Jaw BZ1308
- 2. Chain NSS
- 3. Tooth Insert BTI12520-



BT2000 2" Thinwall

- 1. Shoe CK341900
- 2. Jaw BZ13081
- 3. Chain NSS Strap & Roller Assembly - BF42
- 4. Shaft
- 5. Steel Roller
- 6. Strap } BF48
- 7. Hairpin
- 8. Follow Bar BZ1345
- 9. Tooth Insert BTI12520

REPAIR AND SERVICE INSTRUCTIONS: For repair service and parts contact your nearest GARDNER BENDER Service Center. The Service Center will provide complete and prompt service on all GARDNER BENDER products.

PARTS AND SERVICE: For quality workmanship and genuine GARDNER BENDER parts, select an Authorized GB Service Center for your repair needs. Only repairs performed by an Authorized Service Center displaying the official GB Authorized sign are backed with full factory warranty. Contact GARDNER BENDER (800) 624-4320 for the name of the nearest GB Authorized Service Center.

WARRANTY: GARDNER BENDER warrants its products against defects in workmanship and materials for 1 year from date of delivery to user. Chain is not warranted. Warranty does not cover ordinary wear and tear, abuse, misuse, overloading, altered products or use of improper fluid.

WARRANTY RETURN PROCEDURE: When question of warranty claim arises, send the unit to the nearest GB Authorized Service Center for inspection, transportation prepaid. Furnish evidence of purchase date. If the claim comes under the terms of our warranty the Authorized Service Center will REPAIR OR REPLACE PARTS AFFECTED and return the unit

prepaid.M

